


Abatible horizontal 135 f60

							
7820000 (16x)	7814995 (34x)	7837566 (4x)	7822500 (6x)	7806812 (8x)	7806832 (4x)	7806890 (4x)	7806831 (4x)
							
7820005 (18x)	7837502 (8x)	7848845 (8x)	7837564 (16x)	7848511 (16x)	7837505 (2x)	7845521 (2x)	7800002 (34x)
							
7800521 (8x)	7842510 (2x)	7851720 (15x)	7852130 (26x)	7852150 (5x)			



SR. MONTADOR, ANTE CUALQUIER DUDA O SUGERENCIA, ROGAMOS NOS LA HAGA

COD -694


SABER AL DTO. DE ATENCIÓN AL CLIENTE, TELEFONO QUE FIGURA EN LA CAJA DE HERRAJES. GRACIAS (21/10/2014)

Abatible horizontal 135 f60


3

Este paso es **IMPRESINDIBLE** para su seguridad.


El sistema de sujeción a la pared, no es apto para paredes de pladur.



4



5



SR. MONTADOR, ANTE CUALQUIER DUDA O SUGERENCIA, ROGAMOS NOS LA HAGA

SABER AL DTO. DE ATENCIÓN AL CLIENTE, TELEFONO QUE FIGURA EN LA CAJA DE HERRAJES. GRACIAS (21/10/2014)

COD -694